



Picture 1 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Manure transfer area on the east side of the barns.



Picture 2 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Manure transfer area on the east side of the barns (flow toward the drain).



Picture 3 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Drain on the concrete pad, partially covered in solids, on the east side manure transfer area.



Picture 4 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Vegetated drainage ditch (looking south) that receives runoff from the manure transfer areas.



Picture 5 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Manure transfer area on the west side of the barns.



Picture 6 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Drain on the concrete pad in the west side manure transfer area.



Picture 7 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
View of silage bunkers, graded toward the silage leachate/runoff collection system.



Picture 8 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Silage leachate/runoff collection system, with water pooling around the concrete drain bay.



Picture 9 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Solids build-up at the concrete drain bay for the silage runoff collection system.



Picture 10 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Solids accumulated and channeling in the high-flow treatment area.



Picture 11 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Solids accumulated in the silage collection system's high-flow treatment area.



Picture 12 – Foster Brothers Farm, 58 Lower Foote Rd., Middlebury, VT – 07/29/14  
Remote manure pit, located east of the main farm.